CITY OF PORTLAND

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager				Inspector		Inspection Date		
TRIPALDI VICTORIA A C				Jon Rioux		4/12/2007		
Locatation CBL			Status		Inspection Type			
14 IRVING ST 129 B008001			Re-Inspect 30 Days		Complaint-Housing Inspection			
	Code	Int/Ext		Floor	Unit No.	Area	Compliance Date	
1)	6-108.1	Exterior					Various locations	
	Violation:	Foundations cellars, exterior walls, roofs						
	Notes:	Every exterior wall and roof shall be substantially weathertight, watertight, and vermin proof. Water from roofs shall be so drained and conveyed therefrom as not to cause repeatedly wet floors, walls, or ceilings, or hazard to adjacent buildings or the occupants thereof.						
2)	6-108.2	Interior		Various locations				
	Violation:	Interior floors, walls, ceilings and doors						
	Notes:	Every floor wall, ceiling, and door shall be in a structurally sound condition and in good repair and shall be substantially vermin proof. This shall include the suspended ceiling near Apt. # 2 and the back entryway, and all interior walls and ceilings damaged by the leaking roof.						
3)	6-113.5	Interior		Basement				
	Violation:	Maintenance of lighting fixtures						
	Notes:	Eliminate all obsolete/ discontinued wired.						

Comments: