CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

June 11, 2018

Location	CBL	Inspection Date
36 IRVING ST	129 B009001	4/5/2018
Inspector	Inspection Type	Status

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 6/30/2018.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation. All apartments need to be numbered.	//
NFPA 101-7.2.4.3.1 FIRE BARRIER REQUIRES MAINTENANCE ; Fire barriers separating buildings or areas between which there are horizontal exits shall have a minimum 2-hour fire resistance rating, unless otherwise provided in 7.2.4.4.1, and shall provide a separation that is continuous to the finished grounded level. Panel needed to cover knee wall access into front stairwell on 3rd floor.	//
NFPA 101- 7.2.1.8.1 FIRE DOORS MUST BE SELF- OR AUTO-CLOSING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise permitted by 7.2.1.8.3. All fire doors need to auto-close and latch.	/
NFPA 101- 31.3.2.1.1 BOILER PROTECTION REQUIRED; The areas described in Table 31.3.2.1.1 shall be protected as indicated: Boiler and fuel-fired heater rooms serving more than a single dwelling unit (minimum separation/protection is 1 hour or sprinklers) Over all fuel fired heating unts in the basement. Shut off valves recommended.	//
NFPA 101- 8.3.4.2 60 MINUTE FIRE DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 that states fire door assemblies for vertical shafts (including stairways, exits, and refuse chutes) are rated and required for 1 hour. Basement door rear stairwell.	//

Violation		Proposed Date of Completion
connectors to combustible mate through 9.5.5.3 for both unprote	PROTECTION NOT PROVIDED; Clearances from erial shall be in accordance with the requirements of 9.5.1.1 cted and protected installations. g all heating units in the basement.	
NFPA 54- 5.6.1.1 IMPROPER F systems shall comply with the reauthority having jurisdiction.	PIPING USED FOR NAT. GAS; Materials used for piping equirements of this chapter or shall be acceptable to the atter heater in center of basement needs to be rerouted out of	
FINAL DATE OF COMPLETED	O VIOLATION(S)	//
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
sufficient financial and techniquestions. VIOLATOR CERTIFICAT I agree to remedy the violation	to reject or modify any proposed plan of action, and may ical capacity to complete the proposed plan. Please contaction. CION This listed within the timeframes provided. If I require addition the Fire Prevention Bureau prior to the deadline to require.	t the Bureau with any itional time to comply, itional time to comply, itional time to comply, it
is entirely within the Bureau' I further understand that it is	s discretion to grant or deny. s my responsibility to schedule a reinspection of my proper My failure to schedule a reinspection shall be deemed an	rty once the violations
	reement, I understand that I am liable for penalties pursus \S § 1-15 and 10-25, and 30-A M.R.S. \S 4452 and may be .	
Date	Responsible Party	
Date SEEN AND AGREED	Responsible Party	
Date	Fire Prevention Bureau	