

21-25 PLEASANT AVENUE



Full cut # 920R - Half cut # 9202R - Third cut # 9203R - Fifth cut # 9205R

PERMIT TO INSTALL PLUMBING

PERMIT NUMBER **1343**

Date Issued **10/18/77**
 Portland Plumbing Inspector
 By **ERNOLD R GOODWIN**

Address **21 Pleasant st.**
 Installation of
 Owner of Bldg **Reggie Osborn**
 Owner's Address **Same**

App. First Insp.

NEW	REPL		NO	FEE
		SINKS		
	x	LAVATORIES	1	2.00
	x	TOILETS	1	2.00
		BATH TUBS		
		SHOWERS		
		DRAINS - FLOOR SURFACE		
		HOT WATER TANKS		
		TANKLESS WATER HEATERS		
		GARBAGE DISPOSALS		
		SEPTIC TANKS		
		HOUSE SEWERS		
		ROOF LEADERS		
		AUTOMATIC WASHERS		
		DISHWASHERS		
		OTHER		
		Base Fee		3.69
		TOTAL		7.00

Date
 By

App. Final Insp.

Date
 By

Type of Bldg.

- Commercial
- Residential
- Single
- Multi Family
- New Construction
- Remodeling

Building and Inspection Services Dept.: Plumbing Inspection



RESIDENCE ZONE-C

APPLICATION FOR PERMIT

Class of Building or Type of Structure ... third class

Portland, Maine, March 20, 1951

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 25 Pleasant Avenue Within Fire Limits? no Dist. No. Owner's name and address Jennie W. Hinton, 25 Pleasant Ave. Telephone Lessee's name and address Contractor's name and address William H. A. Hinton, 150 Francis Street Telephone Architect Specifications Plans no No. of sheets Proposed use of building Tenement No. families 3 Last use " " No. families 3 Material frame No. stories Heat Style of roof Roofing Other buildings on same lot Estimated cost \$ 10. Fee \$.50

General Description of New Work

To cut in new door 31" wide on second floor from existing room to hall.

Chief's order and appl with drawn. Refund when receipt returned. Chief's order 2/16/51 Refund 3/26/51 3/23/51 Sent to Fire Dept. 3/20/51 Paid from Fire Dept. 3/24/51

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO owner

Details of New Work

Is any plumbing involved in this work? Is any electrical work involved in this work? Height average grade to top of plate Height average grade to highest point of roof Size, front depth No. stories solid or filled land? earth or rock? Material of foundation Thickness, top bottom cellar Material of underpinning Height Thickness Kind of roof Rise per foot Roof covering No. of chimneys Material of chimneys of lining Kind of heat fuel Framing lumber—Kind Dressed or full size? Corner posts Sills Girt or ledger board? Size Girders Size Columns under girders Size Max. on centers Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet. Joists and rafters: 1st floor, 2nd, 3rd, roof On centers: 1st floor, 2nd, 3rd, roof Maximum span: 1st floor, 2nd, 3rd, roof If one story building with masonry walls, thickness of walls? height?

If a Garage

No. cars now accommodated on same lot, to be accommodated number commercial cars to be accommodated Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

APPROVED: [Signature lines]

Miscellaneous

Will work require disturbing of any tree on a public street? no Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

INSPECTION COPY

Signature of owner

Jennie W. Hinton By J. W. Hinton

Permit No. 511
Location 25 Pleasant Ave
Owner Jessie K. Stanton
Date of permit 1/51
Notif. closing-in _____
Inspn. closing-in _____
Final Notif. _____
Final Inspn. _____
Cert. of Occupancy issued _____

NOTES