Portland, Maine



Yes. Life's good here.

Planning & Urban Development Department

Director of Planning and Urban Development Jeff Levine

> Inspection Services, Director Tammy M. Munson

RICE GEOFFREY I 657 CONGRESS ST 1ST FLOOR PORTLAND, ME 04101

CBL: 132 J001001

Located at: 197 PLEASANT AVE

Dear Rice Geoffrey I,

NOTICE OF INTENT TO PROSECUTE

An evaluation of the above-referenced property on 12/19/2014 revealed that the structure and premises fails to comply with previous violation notices sent to you. Attached is a list of those violations.

The property continues to be in violation of Article V. Of the Housing Code of the City of Portland. All referenced violations shall be corrected within 5 days of the date of this notice. A reat which time compliance will be required. inspection of the premises will occur on

This is a notice of intent to prosecute. The matter is being referred to the City of Portland Corporation Counsel for legal actioon and possible civil penalties, as provided for in Section 1-15 of the Code, and in Title 30-A M.R.S.A. ss 4452.

Please be advised that because this is a letter of intent to prosecute, and that Section 6.2 of the Code requires that you pay a \$150.00 re-inspection fee due to the repeated violations.

. Failure to pay the assessed fee within 30 days shall cause This must be paid prior to the City to assess a lien against the property pursuant to Section 1-16 of the Code.

Please feel free to contact me if you have any questions or would like to discuss this matter further.

Sincerely, R. Plessings.

Graig R. Messinger.

CITY OF PORTLAND PORTLAND FIRE DEPARTMENT

390 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager RICE GEOFFREY I				Inspector John Marte	ell	Inspection Date 11/17/2014	
Location				Status		Inspection Type	
197 PLEASANT AVE 132 J001001		001001	Failed		Fire Prevention-FP Routine Inspe		
Code	int	/Ext	Floor	. Unit No.	Area	Compliance Date	
1) 9.002 Violation: Notes:	Interior 12/22/2014 1-HOUR FIRE DOORS ASSEMBLIES REQ; 1-HOUR FIRE DOORS ASSEMBLIES REQUIRED 1-HOUR FIRE DOORS ASSEMBLIES REQUIREDFIRE DOORS ON ALL UNITS AND ENTRIES TO BASEMENTS NEED TO BE I HOUR FIRE RATED DOORS WITH SELF CLOSING HINDGES.						
2) 6.002 Violation: Notes:	Interior Basement OPEN ELECTRICAL JUNCTION BOX; ELECTRICAL COVERS IN BASEMENT ELECTRICAL COVERS IN BASEMENTALL OPEN WIRES NEED TO TERMINATE IN JUNCTION BOX OR BE REMOVED IF NOT IN SERVICE. VIOLATION THROUGHOUT BOTH BASEMENT AREAS.						
3) 55.530 Violation: Notes:	Interior LABEL UNIT DOORS; LABEL UNIT DOORS LABEL UNIT DOORSLABEL UNIT DOORS, SOME DOORS MISSING NUMBERS. ALSO NEED CONTRASTING NUMBER ON EXTERIOR DOOR TO IDENTIFY DWELLING FROM STREET.						
4) 55.390 Violation: Notes:	Interior PROTECTION SPRINKLER HEAD REQUIRED OVER BOILER IN BASEMENT AND ALSO GAS FIRED HOT WATER HEATERS.						
5) 55.125 Violation: Notes:	Interior REPAIR CORRIDOR WALLS; REPAIR CORRIDOR WALLS REPAIR CORRIDOR WALLSHOLES IN BASEMENT STAIRS, FILL CHASES IN BASEMENT, HOLE IN MOP ROOM CLOSET IN FIRST FLOOR HALLWAY.						
6) 55.040 Violation: Notes:	Interior VERTICLE OPENING VIOLATION; VERTICLE OPENING VIOLATION VERTICLE OPENING VIOLATIONI HOUR FIRST SEPERATION NEEDED BETWEEN 1ST AND 2ND FLOOR HALLWAYS.						
7) 55.140 Violation: Notes:	Interior Laundry Room HAZARDOUS AREAS LAUNDRY ROOM ON 2ND FLOOR NEEDS 1 HOUR SEPERATION FROM MEANS OF EGRESS						
8) 1.130 Violation:	1-4.4.3.2 MEANS OF EGRESS SHALL BE ILLUMINATED; ILLUMINATION OF MEANS OF EGRESS SHALL BE PROVIDED (NORMAL LIGHTING). EXIT SIGNS SHALL BE CONTINUOUSLY ILLUMINATED AND USE AN EMERGENCY LIGHTING SOURCE. HALLWAYS WILL HAVE ADEQUATE ILLUMINATION AT ALLL TIMES.						

CITY OF PORTLAND PORTLAND FIRE DEPARTMENT

390 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
RICE GEOFFREY I		John Martell	11/17/2014
Location	CBL	Status	Inspection Type
197 PLEASANT AVE	132 J001001	Failed	Fire Prevention-FP Routine Inspe

9) 55.162

Violation:

10-1 HARDWIRED SMOKE DETECTORS REQUIRED; HARDWIRED, PHOTOELECTRIC SMOKE

ALARMS WITH BATTERY BACK UP REQ IN EACH SLEEPING ROOM, IMMEDIATELY OUTSIDE

OF THE SLEEPING ROOMS AND WITHIN 21 FEET AND ON EACH LEVEL WITH IN

THEDWELLING UNIT. ALARMS MUST BE INTERCONNECTED WITHIN THE INDIVIDUAL

DWELLING UNIT.

Notes:

HARDWIRED, PHOTOELECTRIC SMOKE ALARMS WITH BATTERY BACK UP REQ IN EACH SLEEPING ROOM, IMMEDIATELY OUTSIDE OF THE SLEEPING ROOMS AND WITHIN 21 FEET AND ON EACH LEVEL WITH IN THEDWELLING UNIT. ALARMS MUST BE INTERCONNECTED

WITHIN THE INDIVIDUAL DWELLING UNIT.

Comments:

Received complaint that there were no fire doors on the units. Review of records in Naviline shows fire doors were writtin up in 2001. Made appointment with Adam Rice, property manager to do inspection today.



<u> </u>					
SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY				
Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. Print your name and address on the reverse so that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits.	A. Signature X				
1. Article Addressed to: No. beoffrey Rice (3) 657 Congress st	De delivery address different from item 1?				
Portland. Me ould	3. Service Type Si Certified Mall ☐ Express Mail ☐ Registered ☐ Return Receipt for Merchandise ☐ Insured Mail ☐ C.O.D.				
	4. Restricted Delivery? (Extra Fee)				
2. Article Number (Transfer from service label) 7012 3050	0000 5606 9815				
2S Form 3811, February 2004 Domestic Return Receipt 102595-02-M-1					