THIS IS NOT A BOUNDARY SURVEY

This copyrighted document expires 03-17-13. Reproduction and/or dissemination after this date is unauthorized. MORTGAGE INSPECTION OF: DEED BOOK __17867__ PAGE _

PLAN BOOK ____ PAGE .

COUNTY __Cumberland

ADDRESS: 33 Brentwood Street, Portland, Maine

Job Number: 749-58

Inspection Date: 12-17-12


Scale: __1" = 30'

Client File #: __resB248

Sellers: Burt/Flanagan

Buyers: Burnap/Fine

1.1/2 story wood structure w/ brick foundation



Note: Lines of occupation are shown. A boundary survey may yield different results.

TO: H&D Title & Closing Services; Residential

Mortgage Services and its title insurer.

Monuments found did not conflict with the deed description.

The dwelling setbacks do not violate town zoning requirements.

As delineated on the Federal Emergency Management Agency Community Panel 230051-0007 C:

The structure does not fall within the special flood hazard zone.

The land does not fall within the special flood hazard zone.

A wetlands study has not been performed.

APPARENT EASEMENTS AND RIGHTS OF WAY ARE SHOWN. OTHER ENCUMBRANCES, RECORDED OR NOT, MAY EXIST. THIS SKETCH WILL NOT REVEAL ABUTTING DEED CONFLICTS, IF ANY.

Livingston-Hughes Professional Land Surveyors 88 Guinea Road · Kennebunkport, Maine 04046

207-967-9761 phone 207-967-4831 fax . www.livingstonhughes.com

THIS SKETCH IS FOR MORTGAGE PURPOSES ONLY