

Permitting and Inspections Department Michael A. Russell, MS, Director

July 7, 2016

DERICE MARIE C 75 CLINTON ST PORTLAND, ME 04103

CBL: 136 B005001

Located at: 75 CLINTON ST

2nd Notice

Dear DERICE MARIE C,

An evaluation of the above-referenced property on 05/24/2016 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations. This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 14days of the date of this notice. A reinspection of the premises will occur on 07/25/2016 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code. This constitutes an appealable decision pursuant to Section 6-127 of the Code. Please feel free to contact me if you wish to discuss the matter or have any questions. Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

/s/

Brian Laflamme Electrical Inspector 874-8703 B. K J. Film



Permitting and Inspections Department Michael A. Russell, MS, Director

VIOLATIONS

The service entrance cable outer sheath is completely removed and poses an electrocution hazard and needs to be replaced immediately.

Sincerely,

ISI.

Brian Laflamme Electrical Inspector 874-8703