


To establish the boundaries of 114 Mackworth I used an undisturbed 3/4" iron pipe found below grade at the southwest corner of the 114 Mackworth Street as the starting point of the survey. I located a capped by Reginald Parker Professional Land Surveyor of Royal River Surveying in Yarmouth.

The 3/4" inch pipe and capped rebar are both on the northerly right-of-way limits of Mackworth Street. With these two monuments located I was able to compute the missing corners of 114 Mackworth Street using the angles, bearings and distances contained in the legal description of the lot.



Barry M. Allen

Maine Professional Land Surveyor #1271

