COMPLAINT PROCESSING

			CIVIPLAINT PROCESSING	
	Complaint Informat	ion:	11 01	5/12/12
	Address:	20 Sn	mith St-	//>/
	CBL:	021-	E029	/ ?
	Case #	2012-0	04-3875	· ·
	Reporting Party/#	I.D. Sc	vzanne	
	Landlord/Contact/#	Mark R	icci 595-0338	
	Complaint(s):			
Trach	about exterior			
T 1	· IIII	1	Property Information:	M / N D
irash r	seing distributed	by	Owner/LLC	Mark D Ricci
ina fil	being distributed tenant inside	blog.*	Address	P.O. Box 514
				Bridgeton ME 04000
				0
			Inspection Information:	/ /
			Inspection Date	5/1/12
			Inspector	G
			Assisting	
			# Units in Bldg	
			# Units Allowed	Ø
			When did this first occur?	Ø
			How many times?	Ø
			Have you notified LL	Ø

Byear Jun 14 Ptld Housing Julie Gregor *Tennant Ruth Scott

George Froehlich - 20-22 Smith St.

From:

"Julie Gregor" <jgregor@porthouse.org>

To:

<gef@portlandmaine.gov>

Date:

5/15/2012 11:51 AM

Subject: 20-22 Smith St.

George

The inspection report was, surprisingly, minimal except the trash outside and debris in rear hall.

We failed:

- -Missing switch cover in the living room
- -Missing outlet cover in the kitchen
- -Missing outlet cover in the left rear bedroom
- -Repair the damaged wall in the left rear bedroom
- -Tenant Responsibility: Remove the debris from the rear hallway
- Remove the trash from the yard

There was a hardwire smoke detector / CO detector in the unit (what we require) The inspector said the inside of the unit was picked up and didn't appear to be an issue yesterday. Apparently Mark Ricci met the inspector at the building for the inspection and was made aware of our requirements.

I will contact you when we conduct the re-inspection to see if you still need to access the building at that point.

-Julie Gregor Portland Housing Authority Inspection Dept.