Form # P 04

DISPLAY THIS CARD ON PRINCIPAL FRONTAGE OF WORK - 'CITY OF PORTLAND

Please Read	C	II Y OF	POR	ILAI	ND		
Application And Notes, If Any, Attached		B P	ERMI	CTION	Permit	Number: 050869	
	DAIGLE ROBERT G		WCLE ITS /Cr			PERMIT ISS	SUED
•	Remove existing deck			Rooi		AUG - 2 2	2005
AT 77 WELLINGTON RD				G 141	D013001	AUG - 2 2	2005
provided that the of the provisions the construction this department.	s of the Statutes , maintenance a	s of Nam ne an	ation ad of the ildings and	epting ances sucreure	g this pe of the C s, and o	rail shall com ity of Portland f the application	ply with a regulating on file i
Apply to Public World and grade if nature such information.		N fication g hand w b re this l la ed or d H JR NOT	n permis ding or	must n procu therec ed-in. RED.	procu	tificate of occupar red by owner befor part thereof is occ	re this build-
OTHER REQUIR	ED APPROVALS						12/05
Health Dept.							9
Appeal Board			•		-CA	Q-//	
OtherDepartm	nent Name			 	Dijecto	r - Building & Inspection Service	es
	P	PENALTY FOR	REMOVING	THIS CA	RD 🛴)	

City of Portland, N		0			Permit No:	869	BERM	17 155	304	BL:	0013001
Location of Construction:	Street, 04101 Tel: (207) 874-8703, Fax: (207) 874-871 (2			· · · ·	wner Addres	├	AUG	- 2	<u>200₹</u>		+
77 WELLINGTON RD DAIGLE ROBERT G & MARGO				77 WELLIN	1		- <u>L</u>	COUV			
Business Name: Contractor Name:		C	ontractor Ad	ress:	OLTY OF	DOE	, , 	KKITA.	1		
Craig Hamme		nd	n l	Contractor Address: CITY OF P Permit Type:			PU	114	2076 534		
Lessee/Buyer s Name	see/Buyer's Name Phone:			Additions -	Dwell	lings				R-3	
Past Use:		Proposed Use:		Ī	Permit Fee: Cost of Work: CEO District:					7	
			Single Family / Remove exisitng deck for addition of Kitchen and Dining Room		\$381.00 \$40,000.00 4						
	deck for additi				FIRE DEPT: Approved Us				SPECTION: se Group: [1-3] Type: \$78 TRC 7203		
Proposed Project Description	nr:				\mathcal{N}	1 /	7	1.7	_K	- W	1
Remove existing deck		of Kitchen and Dir	ning Ro	om s	Signature: Signature:			Signati	gnature:		
			8	L-	PEDESTRIAN	ACTIV	VITIES DIS				
					Action:	Approv	ed [] Ap	proved w	/Cond	litions] Denied
				S	Signature:				Date:		
Permit Taken By:	Date A	te Applied For:			Zo	ning	Approva	 al			
dmartin	06/2	29/2005									
			Spe	cial Zone or Reviews	S	Zonin	g Appeal		H ,	listoric Pro	eservation
				oreland	☐ Miscellaneous ☐ Does N ☐ Conditional Use ☐ Requir			Not in District or Landmark			
			□ w	etland			Does Not R	Require Review			
			☐ Flo	oor Zone			Requires Review				
			☐ Su	bdivision			Approved				
			☐ Sit	aDian	Approved Approved			v/Conditions			
			Мај	Minor MM	ם 🗌 ד	enied				Denied	//
		$_{\rm late:}$ $^{\rm late:}$			late:				Date: 8/1/05		
				' '						' T	
				ERTIFICATIO	NT.						
I hereby certify that I an I have been authorized by burisdiction. In addition shall have the authority such permit.	by the owner a, if a permit f	to make this appli for work described	med pro ication a d in the	operty, or that the is his authorized a application is issu	proposed w gent and I a led, I certify	gree to	o conform he code of	to all a ficial's	pplic autho	able laws orized rep	s of this presentative
SIGNATURE OF APPLICA	NT			ADDRESS			DATE	ξ.			ONE

PHONE

DATE

RESPONSIBLE PERSON IN CHARGE OF WORK, TITLE

City of Portland, Maine - Building or Use Permit			Permit No:	Date Applied For:	CBL:		
389 Congress Street, 04101 Tel:	(207) 874-8703, Fax: (6 05-0869	06/29/2005	141 D013001			
Location of Construction:	ocation of Construction: Owner Name: O				Phone:		
77 WELLINGTON RD	DAIGLE ROBERT G	& MARGOT	77 WELLINGTON RD				
Business Name:	Contractor Name:		Contractor Address:	Phone			
	Craig Hammond			(207) 653-4106			
essee/Buyer's Name Phone: P			Permit Type:				
			Additions - Dwellings				
'roposed Use:							
Single Family / Remove exisiting ded Dining Room	k for addition of Kitchen	and Remo	ve existing deck for	r addition of Kitcher	and Dining Room		
Dept: Zoning Status:	Approved	Reviewer	: Tammy Munson	Approval D	Date: 0810212005		
Note:					Okto Issue: 🗹		
Dept: Building Status: Note:	Approved with Condition	Reviewer	: Tammy Munson	Approval D	Oate: 08/02/2005 Okto Issue: ✓		
1) The sauna tubes must be a minin	num of 48" below grade.						

Comments:

7/21/05-tmm: left message w/builder - need framing detail on side entry porch/stair

7/22/05-tmm: spoke w/builder - need framing detail on side entry porch 8/2/05-dmartin: Owner brought in the plans for side stoop today/ dm



All Purpose Building Permit Application

If you or the property owner owes real estate or personal property taxes or user charges on any property within the City, payment arrangements must be made before permits of any kind are accepted.

Square Footage of Lot

Location/Address of Construction:

Total Square Footage of Proposed Structure

450 S, Ft.		15	,750 3	, F-1	
Tax Assessor's Chart, Block & Lot Chart# Block# Lot# MAP 141 Block D Lots 1314.15	Owner:	a Mars	of Daisle	Telephone 20) · >> :	e: 5-0880 ^{हर} 1-30>5 प
Lessee/Buyer's Name (If Applicable)	Robert C	name, address	elinstan Ro	Cost Of Work: \$ 40, Fee: \$ 38	
Current use: Home Single	Family				
F the location is currently vacant, what wa	as prior use:				
Proposed use: Kitche Project description: Remove Existing	int: E Deck	to Add	,1	_	
Contractor's name, address & telephone: Who should we contact when the permit Mailing address:					
We will contact you by phone when the preview the requirements before starting and a \$100.00 fee if any work starts before	ny work, witl	h a Plan Reviev	ver. A stop wo		
F THE REQUIRED INFORMATION IS NOT INCL DENIED AT THE DISCRETION OF THE BUILDING NFORMATION IN ORDER TO APROVE THIS P	PLANNING				_
Signature of applicant:	ر		Date: 6/	28/05 <u> </u>	
of Building MSPECTURE District you may n அல்கள் அதித்தில் District you may Planning Depa	ay be sub	ject to additi	onal permi	permit is iss tting and fee	sued. s with the
JUN 2 9 2005		14	15/		
ハヒしたハノトハ (

Please call 874-8703 or 874-8693 to schedule your inspections as agreed upon

Permits expire in 6 months, if the project is not started or ceases for 6 months.

The Owner or their designee is required to notify the inspections office for the following inspections and provide adequate notice. Notice must be called in 48-72 hours in advance in order to schedule an inspection:

By initializing at each inspection time, you are agreeing that you understand the inspection procedure and additional fees from a "Stop Work Order" and "Stop Work Order Release" will be incurred if the procedure is not followed as stated below.

A Pre-construction Meeting will take place upon receipt of your building permit.

Footing/Building Location Inspection:

Prior to pouring concrete

Re-Bar Schedule Inspection:

Prior to pouring concrete

Foundation Inspection:

Prior to placing ANY backfill

Framing/Rough Plumbing/Electrical:

Prior to any insulating or drywalling

Final/Certificate of Occupancy:

Prior to any occupancy of the structure or use. NOTE: There is a \$75.00 fee per inspection at this point.

Certificate of Occupancy is not required for certain projects. Your inspector can advise you if your project requires a Certificate of Occupancy. All projects DO require a final inspection

Action If any of the inspections do not occur, the project cannot go on to the next phase, REGARDLESS OF THE NOTICE OR CIRCUMSTANCES.

CERIFICATE OF OCCUPANICES MUST BE ISSUED AND PAID FOR, BEFORE THE SPACE MAY BE OCCUPIED

Signature of Applicant/Designee

Signature of Inspections Official

Building Permit #: _

*- Inspector re: min. 48 hour notice: M-Th only.
- Jonathan Reed.

This page contains a detailed description of the Parcel ID you selected. Press the **New Search** button at the bottom of the screen to submit a new query.

Current Owner Information

Card Number 1 of 1
Parcel ID 141 DOL3001

Location 77 WELLINGTON RD
Land Use SINGLE FANILY

Owner Address DAIGLE ROBERT G 8 NARGOT B DAIGLE JTS

77 WELLINGTON RD PORTLAND NE 04103

Book/Page 21625/171

Legal 141-0-13-14-15
WELLINGTON RD 77

15750 SF

Current Valuation Information

Land Building Total \$37,490 \$90.190 \$127,680

New Estimated Valuation Information

Land Building Total Phase-In Value #76,400 #177,300 #253,700 #190,690

Property Information

Year Built Style Story Height Sq. Ft Total Acres
1933 Old Style 2 2090 0.362

Bedrooms Full Baths Half Baths Total Rooms Attic Basement 5 2 9 None Full

Outbuildings

Type Quantity Year Built Size Grade Condition

Sales Information

Date Type Price Book/Page 08/03/2004 LAND + BLDING \$333,000 21625-171 08/01/2003 LAND + BLDING \$3157000 19990-253


Picture and Sketch


Picture Sketch Tax Map


Click here to view Tax Roll Information.


Any information concerning tax payments should be directed to the Treasury office at **874-8490** or emailed.

Click here to view comparable sales or below to view by:









FRAME SPECIFICATIONS

FLOOR SYSTEM **IOISTS** As INDICATED BRIDGING AT CENTER 2X6 PT SILL W/ SEALER SUBFLOOR AS INDICATED EXTERIOR WALLS 2X6 STUDS AS INDICATED SHEATHING AS INDICATED AIR INFILTRATION WRAP VAPOR BARRIER SIDING/FINISH AS INDICATED INTERIOR WALLS 2X4 STUDS AT 16"OC GYPBOARD AS INDICATED ROOF SYSTEM RAFTERS/TRUSSES AS INDICATED SHEATHING AS INDICATED
15# UNDERLAYMENT ICE SHIELD AT EAVES/VALLEYS 235# SHINGLES AS INDICATED INSULATION EXTERIOR WALLS-RIP ATTIC CAP-R38 SILLS-R19 FROST WALL-2' RIGID = VENTILATION SOFFIT-2" CONT. STRIP RIDGES-CONT. SHINGLE CIRCULATION VENTS BETWEEN RAFTERS/TRUSSES

BEAMS/HEADERS 3-2X6 MAX 40" SPAN L 3-2X8 MAX, 80° SPAN BEAMS AS INDICATED MIN 4" BEARING ALL BEAMS-INTERIOR FINISHES 1/2" GYPBOARD OR AS INDICATED-WALLS/CEILING FLOORING AS INDICATED PAINT/STAIN AS INDICATED

FOUNDATION NOTES

AF10" CONCRETE WALL AS INDICATED ON CONT. KEYED POOTING

2. 40° CONCRETE FROST WALL AS INDICATED ON CONT. KEYED FOOTING

4" CONCRETE SLAB ON 6 MIL VAPOR BARRIER ON 8" MIN GRAN, FILL

CHEMONEY FLUE ON CONC. PAD

3 LO" STEEL LALLY COLUMNS ON 34"YCH"X12" POOTRIGS SLOPE CONC. SLAB 2" TO DOORS OR DRAIN

STEEP WALL DOWN TO GRADE AT 2' MAX DROP MIN RUN

DROP SLAB 4" FROM TOP OF WALL

AFERED PRECAST CONC. PIER, 5' L, PROVIDE POST CAP 2X6 DAYLIGHT BASEMENT WALL ON PT PLATE

11. STRAPS OR ANCHORS AT CORNERS AND 4'OC
12. SUMP PIT W/ 4" DIA. PERPORATED UNDERDRAIN PIPES
BOTH SIDES OF WALL TO SUMP OR DAYLIGHT GRAVITY

13. 4° DIA. PERFORATED RADON PIPES UNDER SLAB AT 20' MAX. OC, CONNECT TO UNDERDRAINS, PROVIDE STUBS

14. CONTROL JOINTS AT MAX. 30" OC WALLS AND SLABS


15. ASPHALT PAINT EXTERIOR WALLS TO GRADE


16. CONCRETE-2500 PSI AT FOOTINGS, 3000 PSI AT WALLS SOIL BEARING-2500 PSF


17. ALL FOOTINGS TO FROST DEPTH AND UNDISTURBED SOIL

REVISIONS

BY








DEPT. OF BUILDING INSPECTION CITY OF PORTLAND, ME

JUN 2 9 2005

RECEIVED





CITY OF PORTLAND, MAINE

Department of Building Inspections

Vinc 29 20 05
Received from House Daigle
Location of Work 77 (ellington
Cost of Construction \$ 40,000
Permit Fee \$
Building (IL) Plumbing (I5) Electrical (I2) Site Plan (U2)
Other
CBL: MI D C13
Check #: Total Collected \$

THIS IS NOT A PERMIT

No work is to be started until PERMIT CARD is actually posted upon the premises. Acceptance of fee is no guarantee that permit will be granted. PRESERVE THIS RECEIPT. In case permit cannot be granted the amount of the fee will be refunded upon return of the receipt less \$10.00 or 10% whichever is greater.

WHITE - Applicant's Copy YELLOW - Office Copy PINK - Permit Copy

671172