


11/4/15



116 Gleckler Rd. Erin Van Houwe Residence: East Elevation - Existing

Contractor: Paul Davis Restoration

Scale = $\frac{1}{4}'' = 1 \text{ Ft}$