


11/4/15

Existing
- Not to be changed



116 Gleckler Rd. Erin Van Horne Residence ; Front Elevation / View From Gleckler Rd.
Contractor : Paul Davis Restoration

Scale: $\frac{1}{4} = 1$ Foot

FIVE STAR. ★★★★★

FIVE STAR. ★★★★★

FIVE STAR. ★★★★★

FIVE STAR. ★★★★★