


11/2/15



116 Glecker Rd. Erin Van Horne Residence: West elevation - Existing
Contractor: Paul Davis Restoration
Scale = 1/4" = 1 Ft