


11/4/15



116 Glecker Rd. Erin Van Henna Residence: Rear Elevation - Proposed
Contractor: Paul Davis Restoration

Scale = 1/4" = 1 Foot