61 gleckler
Portland

CITY OF PORTLAND, MAINE
RESURGAM
Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 10/23/17

Materials List

(2) 10" Sonotubes 6' Deep w/feet

2"X8" PT floor stringers 16" oc w/hangers
3/4" Subfloor 4'x8' T/g and glued

All walls KD 2"X6" 16" oc
All Headers for windows (Tri ply w/2"x10"
Exsterior Door 3/0 6'8" 9 light RH swing

Exsterior sheathing 1/2 OSB 4'x8' w
typar for outer covering.

18' 2"x10" Roof stringers 16" o.c
5/8 Roof plywood w/ clips

25 Year 3 tab Black shingles

Window 30"X 48" Double Hung w/grills

Vinal 3mil siding to match exsisting color.