

Strengthening a Remarkable City, Building a Community for Life . www.portlandmaine.gov

Penny Littell - Director of Planning and Development

November 3, 2008

SARGENT JOHN P VN VET & 103 READ ST PORTLAND, ME 04103

CBL: 141 J014001 Located at 103 READ ST

Certified Mail 70033110000260636554

Dear SARGENT JOHN P VN VET &,

POSTING NOTICE

An evaluation of the above-referenced property on revealed that the structure 10/01/2008 fails to comply with Section 6-120.1 of the Housing Code of the City of Portland.

Attached is a list of the violations, from the inspections division and the Portland Fire Department. This list must be completed and an action plan submitted to this office.

Based on that list, and pursuant to Section 6-120.3, this office declares the dwelling unit is unfit for human habitation. A re-inspection of the premises will occur before occupancy at which time the dwelling unit must be totally vacated and secured from vandalism.

Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code in Title 30-A of M.R.S.A ss 4452.

This constitutes an appealable decision pursuant to Section 6-127 of the Code. Please feel free to contact me if you have any questions or would like to discuss this matter further.

Sincerely,

Mike Menario @ (207) 874-8789

Building Inspector

CITY OF PORTLAND
Fire Department
380 Congress Street
Portland, Maine 04101

-		•	10		
Fire	Inspect	ıon	VIO	l at i	ons

Business 2-3 UNIT Owner/Manager Location 0103 READ ST

Number 233981-0-0 Inspection Type
FP Routine Inspection

CBL

Inspector

BENJAMIN A WALLACE Shift: 005 Unit: C41

SARGENT JOHN P VN VET &		141 J014001 BENJAMIN A WALLACE Shift: 005 Unit: C41				
	Туре	Location	Notification Date	Target Compliance	Actual Compliance	
1	STRUCTURE NEEDS REPAIR	REAR DECKS AND STAIRS	10/16/08			
2	SMOKE DETECTOR VIOLATION	IN AND OUTSIDE OF SLEEPING AREAS PER DISCUSSION ON SITE THIS DATE.	10/16/08			
3	DISCONTINUE USE OF EXTENSION CORDS	THROUGH OUT	10/16/08			
4	1-HOUR FIRE RATED EXIT ENCLOSURES A	DOOR FROM STAIR TO FRONT OFFICE	10/16/08			
5	CERTIFY ELECTRICAL SYSTEM	THROUGH OUT	10/16/08			
6	UNVENTED FUEL FIRED HEATER	THROUGH OUT BUILDING. NOT ALLOWED PER STATE LAW.	10/16/08			
7	FIRE RATING NOT MAINTAINED	SEAL ALL VERTICAL PENETRATIONS	10/16/08			

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager SARGENT JOHN P VN VET & Locatation CBL 103 READ ST 141 J014001		Inspector		-	Inspection Date 10/1/2008			
		Mike Menario						
			Status Re-Inspect 30 Days		Inspection Type Complaint-Inspection			
	Code	Int/Ext		Floor	Unit No.	Area	Compliance Date	
1)	6-113.4	Interior				Various lo	cations	
	Violation:	Extension co	ords.					
	Notes:	Remove all	extension cords					
2)	6-111.1	Interior		•		Basement		
	Violation:	Plumbing st	andards/Basic fac	cilities.				
	Notes:	Hire a Maste	er plumber and re	pair all plumbing in the b	asement			
3)	6-111.1	Interior		1	1	Bathroom		
	Violation:	Plumbing st	andards/Basic fac	cilities.				
	Notes:	Hire a Master plumber and repair all plumbing in the 1st floor bathroom						
4)	6-116.1	Interior				Various lo	cations	
	Violation:	Flammable/	Hazardous Materi	als				
	Notes:	Remove all	gas existing gas p	piping				
5)	6-71	Interior				Various lo	cations	
	Violation:	Enforcement for defective installations						
	Notes:	Hire a State	licensed gas tech	nnician to install the prop	er appliance	es and piping	 	
6)	6-116.5	Interior				Various lo	cations	
	Violation:	Fire Protection						
	Notes:	Rate opening (old doorway) between the office and the hallway on the 1st floor, trating					r, this requires a 1 hour	
7)	6-116.5	Interior				Bedroom		
	Violation:	Fire Protecti	on					
	Notes:	Install interconnected 120 volt smoke detectors with battery backup in every bedroom and two on the main floor of the 1st floor apartment						
8)	6-108.e	Interior				Various lo	cations	
	Violation:	Chimneys, fl	lues and vent.					
	Notes:	Repair and o	close up holes in t	he chimney				
Co				ST OF VIOLATIONS AN PANCY OF THE 1ST FL				
		DEPARTMEN'	T REGULATIONS	ALL COMPLY WITH ALL S, ALL NECESSARY PE JPANCY OF THE SECO	RMITS CON	IPLETED A	ND AN INSPECTION	