CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

September 20, 2017

Responsible Party 1:				
DELTA REALTY CO INC				
380 WARREN AVE				
PORTLAND, ME 04103				
Location	CBL	Inspection Date		
Location 148 WALTON ST	CBL 142 F012001	Inspection Date 9/7/2017		
		•		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 10/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101-7.9 EMERGENCY LIGHTING	
Emergency lights do not illuminate when tested.	
1-14.14 ILLUMINATION OF EXIT SIGNS; EXIT SIGNS SHALL BE CONTINUOUSLY ILLUMINATED AND USE AN EMERGENCY LIGHTING SOURCE. Exit Lights in reception and both garage spaces do not illuminate when tested.	
NFPA 54- 9.6.4 UTILITY DISCONNECTS BLOCKED; Each appliance connected to a piping system shall have an accessible, approved manual shutoff valve with a nondisplaceable valve member, or a listed gas convenience outlet. Appliance shutoff valves and convenience outlets shall serve a single appliance only and shall be installed in accordance with 9.6.4.1. Electrical Panel in second garage space blocked by air compressor.	//
NFPA 70- ARTICLE 314.28 OPEN ELECTRICAL JUNCTION BOX; Boxes and conduit bodies used as pull or junction boxes shall comply with 314.28 (A) through (D). Outlet in space between reception and the garage needs cover plate.	//
N.F.P.A. 101- 36.3.5.3., 37.7.3. FIRE EXTINGUISHERS REQUIRED; Portable fire extinguishers shall be provided in all mercantile occupancies in accordance with NFPA 101-36.3.5.3. Extinguisher Training: Employees of mercantile occupancies shall be periodically instructed in the use of portable fire extinguishers. The second garage space has no fire extinguishers.	

Violation		Proposed Date of Completion
monitoring of fire extinguishers sha Location in designated place (2) No reading or indicator in the operable hefting for self-expelling-type exting (5) Condition of tires, wheels, carria	HER NOT ACCESSIBLE; Periodic inspection or electronic all include a check of at least the following items: (1) to obstruction to access or visibility (3) Pressure gauge range or position (4) Fullness determined by weighing guishers, cartridge-operated extinguishers, and pump tanks age, hose, and nozzle for wheeled extinguishers (6) guishers using push-to-test pressure indicators e garage obstructed.	
FINAL DATE OF COMPLETED VI	OLATION(S)	//
FIRE PREVENTION BUREAU RE	-INSPECTION OF COMPLETED VIOLATION(S)	//
questions. VIOLATOR CERTIFICATION I agree to remedy the violations understand that I must contact the is entirely within the Bureau's description of the interval of the int	listed within the timeframes provided. If I require addine Fire Prevention Bureau <u>prior to the deadline</u> to requiscretion to grant or deny. Sy responsibility to schedule a reinspection of my property failure to schedule a reinspection shall be deemed an	itional time to comply, I lest an extension, which rty once the violations admission that the
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	