

# Quality Assurance Labs Inc.

NON-DESTRUCTIVE TESTING AND INSPECTION SERVICES

80 PLEASANT AVENUE • SOUTH PORTLAND, MAINE 04106 • TEL: (207) 799-8911 • FAX: (207) 799-7251

## INSPECTION REPORT

CUSTOMER: SUMMIT GEO TECH		PAGE 1 OF 1
ADDRESS: AUGUSTA, ME.		
ATTENTION: DARREL GILMAN		
COPIES:		
PROJECT: U.N.E. BIOMEDICAL RESEARCH FACILITY		
OWNER: U.N.E.		
CONTRACTOR: WRIGHT-RYAN		
JOB No.:	REPORT No.: QAL-08-1180	DATE(S) INSPECTED: 06-17-08

### REMARKS

>>>> VISUAL INSPECTION OF STAIR AREA STRUCTURAL STEEL CONNECTIONS :

> SITE INSPECTION REVEALED THE FOLLOWING RESULTS :

- A) MID-LEVEL HSS 12X6X 3/8 TO COLUMN AT LINE (5) SHOWS (1) MISSING 3/4" HIGH STRENGTH BOLT AND (2) UN-TORQUED 3/4" BOLTS AT SHEAR TAB CONNECTION. REMOVE FIRE - PROOF MATERIAL FOR ADEQUATE ACCESSABILITY TO CONNECTION.
- B) STAIR STRINGERS TO HEADERS SHOW MISSING VERTICLE FIELD WELDS AT (2) LEVELS.

END ITEMS ///

FAA REPAIR STATION NUMBER RX5R187N  
METHOD(S),PROCESS(ES),PROCEDURE(S) MERCURY FREE

ADDITIONAL INFORMATION - SEE ATTACHED:		<input type="checkbox"/> SKETCH(ES)	<input type="checkbox"/> SUPPLEMENTARY SHEETS	<input type="checkbox"/> NDT REPORTS	<input type="checkbox"/> VIDEO
SIGNATURES				CERTIFICATION	DATE
INSPECTOR MICHAEL DREW CWI # 99050211 <i>Michael Drew</i>				ISS.	M O Y
SUPERVISOR					06   19   08