

Quality Assurance Labs Inc.

NON-DESTRUCTIVE TESTING AND INSPECTION SERVICES
 80 PLEASANT AVENUE • SOUTH PORTLAND, MAINE 04106 • TEL: (207) 799-8911 • FAX: (207) 799-7251

INSPECTION REPORT

CUSTOMER: SUMMIT GEO TECH		PAGE 1 OF 1	
ADDRESS: AUGUSTA, ME.			
ATTENTION: DARREL GILMAN			
COPIES:			
PROJECT: U N E PORTLAND CAMPUS - PHARMACY			
OWNER: U N E			
CONTRACTOR: ALLIED / COOK			
JOB No: 14063	REPORT No: QAL-08-1683	P. O. NUMBER:	DATES INSPECTED: 08-14-08, 08-15-08

REMARKS

>>>> SITE VISIT TO PERFORM VISUAL INSPECTION OF STRUCTURAL STEEL CONNECTIONS: REF. PREVIOUS FIELD REPORT DATED 08-08-08 FOR MARKED ITEMS IDENTIFIED FOR ADDITIONAL WORK. GRID LOCATIONS 1-4, A-G TO INCLUDE ALL LEVELS.

> RE-INSPECTION OF ALL PREVIOUSLY IDENTIFIED ITEMS MARKED FOR ADDITIONAL WORK NOW COMPLETE. IE: BOLTED AND WELDED CONNECTIONS EXCEPT MOMENT CONNECTIONS.

> FIRST AND SECOND LEVEL SHEAR STUD INSPECTION REVEALED FAILED STUDS WHICH WERE RE-WELDED AND ACCEPTABLE.

> THIRD LEVEL SHEAR STUDS REVEALED (14) FAILED STUDS TO BE RE-WELDED.

COMPLETED ITEMS COMPLY WITH SITE DOCUMENTS AND AWS D1.1 REQUIREMENTS FOR VISUAL ACCEPTANCE.

END ITEMS ///

FAA REPAIR STATION NUMBER RX5R187N
 METHOD(S), PROCESS(ES), PROCEDURE(S) MERCURY FREE

ADDITIONAL INFORMATION - SEE ATTACHED: SKETCHES SUPPLEMENTARY SHEET(S) NDT REPORTS VIDEO

SIGNATURES		CERTIFICATION		DATE		
INSPECTOR MICHAEL DREW CWI # 99050211 <i>Michael Drew</i>	ASNT	II	08	18	08	
SUPERVISOR						