



Titan Mechanical, Inc.

61184

Customer Service Report

Team Safety

232 Riverside Industrial Parkway
Portland, Maine 04103
P.O. Box 103
Newport, Maine 04953

Ph: 207-878-5223
Fax: 207-878-5235
Ph: 207-368-2503
Fax: 207-368-2395

Date 7-15-15	Customer #	Unit number or Location	on roof
Customer Name PC Construction		Make	Trane
Address		Model	TTA180C300EA
City, State, Zip		Serial Number	Z144KEAH
Job # 15-482	WorkOrder #		

DESCRIPTION OF WORK PERFORMED

Removed refrigerant from Trane roof top and recovered 18lb of R-22. And removed oil from compressors and put it in waste oil bulked at shop

PO#	QTY	MATERIALS	ENVIRONMENTAL CHECKLIST
54336		Bell/simons gas	<input type="checkbox"/> REFRIGERANT CHARGED lb oz <input checked="" type="checkbox"/> RECOVERED 18 lbs of R-22 <input type="checkbox"/> RECYCLED <input type="checkbox"/> OIL RECOVERY QTS. <input type="checkbox"/> RETURNED <input type="checkbox"/> DISPOSAL <input type="checkbox"/> DISMANTLED <input type="checkbox"/> OTHER
			LABOR AND EXPENSES REGULAR TIME 3.5 OVERTIME MILEAGE 10 JOB EXPENSES

RECOMMENDATIONS

I have the authority to order the work outlined above which has been satisfactorily completed. I agree that Seller retains title to equipment/materials furnished until final payment is made. If payment is not made as agreed, Seller can remove said equipment/materials at Seller's expense and/or impose a 2% liquidation fee on the entire amount contained in the Seller/Buyer transaction. Any damage resulting in said removal shall not be the responsibility of Seller.

WORK COMPLETED? YES NO TECHNICIAN NAME **Dennis Vachon**

Customer Signature _____ Date _____

CUSTOMER



Titan Mechanical, Inc.

61323

Customer Service Report

Team Safety

232 Riverside Industrial Parkway
Portland, Maine 04103
P.O. Box 103
Newport, Maine 04953

Ph: 207-878-5223
Fax: 207-878-5235
Ph: 207-368-2503
Fax: 207-368-2395

Date <u>7/15/15</u>	Customer #	Unit number or Location
Customer Name <u>P4C Construction</u>		Make <u>York</u>
Address		Model <u>PA13NR060-H</u>
City, State, Zip <u>Portland</u>		Serial Number <u>3508X51661</u>
Job #	WorkOrder #	

DESCRIPTION OF WORK PERFORMED

Recover R-22 from rooftop units at old Salvation Army store on Forest Av. Drained oil from compressors after.

PO#	QTY	MATERIALS	ENVIRONMENTAL CHECKLIST
			<input type="checkbox"/> REFRIGERANT CHARGED lb oz
			<input checked="" type="checkbox"/> RECOVERED
			<input type="checkbox"/> RECYCLED
			<input checked="" type="checkbox"/> OIL RECOVERY QTS.
			<input type="checkbox"/> RETURNED
			<input type="checkbox"/> DISPOSAL
			<input type="checkbox"/> DISMANTLED
			<input type="checkbox"/> OTHER
			LABOR AND EXPENSES
			REGULAR TIME <u>3.5</u>
			OVERTIME
			MILEAGE <u>10</u>
			JOB EXPENSES

RECOMMENDATIONS

I have the authority to order the work outlined above which has been satisfactorily completed. I agree that Seller retains title to equipment/materials furnished until final payment is made. If payment is not made as agreed, Seller can remove said equipment/materials at Seller's expense and/or impose a 2% liquidation fee on the entire amount contained in the Seller/Buyer transaction. Any damage resulting in said removal shall not be the responsibility of Seller.

WORK COMPLETED? YES NO TECHNICIAN NAME Bill Lester

Customer Signature [Signature] Date 7/15/15

CUSTOMER