

Field Report

The Park Danforth

Project No: 13-059-00

Portland ME

Field Report No: 2

To: Mark Donovan
 PC Construction
 131 Presumpscot Street
 Portland ME

Time of Visit: 9:00 AM
Date of Visit: 11/24/2015
Weather: Sunny, Cold (40F)

Submitted by: Scott Timmons

Copies:

Present: Scott Timmons (LBA); Ron Norton (CMCS)

Andrew Pires PC Construction
 Kemp Carey PC Construction

Item	Description	Status:
2.1	<p><u>WORK IN PROGRESS</u></p> <ul style="list-style-type: none"> a. CIP concrete footing placement along E-Line, from 11-Line up to approx 7.5 Line b. CIP concrete footing placement for Forest Ave terrace appears to have been installed c. Footing formwork and reinforcing steel underway along A-line, from Knuckle to about 2.5 Line d. CIP foundation wall formwork in progress extending full length of H-Line e. CIP foundation wall formwork in progress along E-Line, from approx 10.8 - 7.8 f. CIP footing formwork in progress for a number of interior column footings in East wing. 	Observation

Attached Sketches:



Footing placement at Main Electrical Room G013

A



Tower construction site (from Arbor Street looking South)

B



Footing formwork and reinforcing along A-Line

A



Foundations along E-Line (elevator B shaft is center of view)

B



Foundations along E-Line near Main electrical room G013

A



Wall formwork progress along H-Line (courtyard side)

B