

# Field Report

**The Park Danforth** **Project No:** 13-059-00  
**Portland ME** **Field Report No:** 3

**To:** Mark Donovan **Time of Visit:** 12:30 PM  
 PC Construction **Date of Visit:** 12/8/2015  
 131 Presumpscot Street **Weather:** M Cloudy, Cool (40deg)  
 Portland ME

**Submitted by:** Scott Timmons **Copies:**  
**Present:** Scott Timmons (LBA) Ron Norton Construction Management Consultin  
Andrew Pires PC Construction  
Kemp Carey PC Construction

Item	Description	Status:
3.1	<p><b><u>WORK IN PROGRESS</u></b></p> <ul style="list-style-type: none"> <li>a. CIP foundation wall formwork in progress along E-Line, from approx 7.8 to 5.6 Line</li> <li>b. CIP concrete footing placement and wall reinforcing along A-Line</li> <li>c. CIP foundation wall formwork along A-Line, from 5.6 Line to approx 4-Line</li> <li>d. Footing formwork and reinforcing steel underway along D-Line from approx 2.5-Line to knuckle</li> <li>e. Elevator B pit wall formwork appears underway</li> </ul>	Observation

**Attached Sketches:**



Tower construction site (from Arbor Street looking south)

**A**



Progress of foundations along west wing of tower.

**B**



CIP footing and wall reinforcement along A-Line

A



Wall formwork along E-Line

B



Wall formwork along E-Line

**A**

**B**