

Field Report

The Park Danforth **Project No:** 13-059-00
Portland ME **Field Report No:** 6

To: Mark Donovan **Time of Visit:** 9:30 AM
 PC Construction **Date of Visit:** 1/26/2016
 131 Presumpscot Street **Weather:** Sunny, Cold (40F)
 Portland ME

Submitted by: Scott Timmons **Copies:**
Present: Kim McCarthy (LBA), Scott Ron Norton Construction Management Consultin
 Timmons (LBA), Ron Norton Andrew Pires PC Construction
 CMCS, Dan Burne (Becker) Kemp Carey PC Construction

Item	Description	Status:
6.1	<u>WORK IN PROGRESS</u> a. Steel erection underway at west wing of tower through level 2 b. Steel Decking installation (East Tower) level 1 ongoing, level 2 underway c. Formwork for Boiler Room footings underway d. Forest Ave Terrace wall foundation reinforcing ongoing e. Foundation waterproofing ongoing f. Formwork of exterior wall of electrical room along Forest Ave.	Observation
6.2	Main Electrical Room (G013): Northeast CIP foundation wall appears to have a couple of areas where the concrete projects beyond the outside face of wall. Chip/grind/repair as required to allow for proper installation of cavity items & stone veneer. (Reference Photo B page P5 of 5)	Correct Work

Attached Sketches:



Tower from corner of Forest Ave and Arbor Street

A



Tower construction site (From Arbor Street looking South)

B



Steel progression at west wing, tower

A



Boiler Room foundation footing formwork off of west wing garage

B



Garage Level

A



Garage Entrance

B



Tower Steel progression at building knuckle from Forest Ave.

A



Foundation and waterproofing progress along Arbor Street elevation

B



Terrace wall reinforcing and foundation wall waterproofing, Forest Ave.

A



Exterior of electrical room, Forest Ave elevation (Reference Item 6.2)

B