

## FIELD OBSERVATION – FIFTH FLOOR MECHANICAL AND PLUMBING REPORT 08-24-2016

---

**Report Date:** 08/24/2016

**Observation Date/Time:** 08/23/2016 8:00 AM

**AEI Project Number and Name:** 14018 – The Park Danforth

**Report by:** Susan Hathaway

**Contractor:** PC Construction

---

N:\Projects\2014\14018 – Park Danforth\40 Construction\Field Reports\2016-08-22 fifth floor east Mech-Plum FIELD REPORT.docx

**Work In Progress:** Mechanical work in the corridor is in progress. The work inspected within the suites complies with code and is consistent with the intent of the construction documents, except as noted below.

### **Observations/Action items:**


#### Unit 1512

- Insulate Supply duct.



#### General Observation

- Complete exhaust ducts



**END OF FIELD OBSERVATION**