



FIELD OBSERVATION – FOURTH FLOOR IN-WALL AND CEILING ELECTRICAL REPORT 08-24-2016

Report Date: 08/24/2016

Observation Date/Time: 08/22/2016 9:30 AM

AEI Project Number and Name: 14018 – The Park Danforth

Report by: Stephen Markiewicz

Contractor: PC Construction

N:\Projects\2014\14018 - Park Danforth\40 Construction\Field Reports\2016-08-22 fifth floor east in-wall and ceiling elec FIELD REPORT.docx

Work In Progress:

Electrical rough-in above ceilings and within walls is substantially complete on the east end of the fifth floor, from column Line 7 to the exterior wall; rough-in of the remainder of the fifth floor is in progress and was not inspected during this visit. The quality of the installed work is high, and the installation appears to be consistent with code requirements and the Contract Documents except as noted below.

Observations/Action items:

Unit 1511:

- Firestop MC penetration through floor in closet wall abutting shower.
- Firestop MC penetration through wall into corridor near unit entrance.

Unit 1512

- Firestopping through floor at bedroom receptacle on wall abutting kitchen is properly sealed.

END OF FIELD OBSERVATION