CITY OF PORTLAND

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

0	wner/Manag	jer		Inspector		Inspection Date	
WOJCIK JOSEPH B &				Jon Rioux		5/17/2007	
Locatation CBL			Status		Inspection Type		
61 UNIVERSITY ST			151 D010001	Re-Inspect 30 Days		Complaint-Inspection	
	Code	Int/Ext		Floor	Unit No.	Area	Compliance Date
1)	6-108.4 Violation: Notes:	Exterior Porch Stairways, stairwells, stairs, porches. Repair the outside porch so that is structurally sound, in good repair, and safe to use.					
2)	6-108.3 Violation: Notes:	Exterior Exterior windows, doors and skylights Maintain the rear porch sliding door so that it is substantially weathertight, watertight, vermin proof and in sound working condition and good repair.					
3)	6-108.2 Violation: Notes:	Interior Interior floors, walls, ceilings and doors Repair the kitchen ceiling so that it is structurally sound and in good repair. The damage appears to be from a previous leak in the upstairs bathroom.					
4)	6-116.5 Violation: Notes:	Interior Fire Protection Replace or repair the hard-wire smoke detector in the common area on the second floor, so that it is in sound working condition, within ten (10) days of this notice.					
5)	6-111.4 Violation: Notes:	Repair the ba	of plumbing fixture athroom sink so tha vith the state plumb	t it is sound mechanica	al condition, 1	Bathroom	cts, leaks and in
Со		Il items shall be corrected within thirty (30) days of this notice, except repairing and or replacing the ardwire smoke detector (within ten 10 days), as agreed on with Mr. Wojcik.					