

5/21/03 Setback inspection and some tubs done - okay -
showing 48" - setback AS' AS shown in plan JG/KW

1/5/04 Complete OK to close JG