CITY OF PORTLAND, MAINE · RESURGAM
Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 04/21/17

Photo # 1 – North elevation

Photo #2 – Southwest corner

Photo # 3 – West elevation

Photo #4 – Basement window near north end of west endwall

Photo # 5 – Basement window at middle of west endwall

Photo #6– Existing 1st floor joist bearing on foundation sill