



0 50 100ft

2,924,474.083 311,590.636 Feet











Permitting and Inspections Department





Permitting and Inspections Departm Approved with Conditions 12/26/2018 20-Fall Brook 12 Bath T= toilet 322-T 56 32 INCARD 5 22 Inchos S= SINK 22 INCHO ANOY From +48 tulet The 1/2 bath Location 15 Shown on Page 1