

**CITY OF PORTLAND**  
**DEPARTMENT OF PLANNING & URBAN DEVELOPMENT**

389 Congress Street  
 Portland, Maine 04101

**Inspection Violations**

<b>Owner/Manager</b> LUCARIELLO VINCENT E JR		<b>Inspector</b> Tom Markley	<b>Inspection Date</b> 12/8/2005
<b>Location</b> 74 ILLSLEY ST	<b>CBL</b> 167 E014001	<b>Status</b> Re-Inspect 30 Days	<b>Inspection Type</b> Building Permit-Housing Inspectio

<b>Code</b>	<b>Int/Ext</b>	<b>Floor</b>	<b>Unit No.</b>	<b>Area</b>	<b>Compliance Date</b>
1) 6-109.4	Exterior			front porch	
<b>Violation:</b>	Disposal of rubbish, garbage and waste.				
<b>Notes:</b>	cardboard on front porch				
2) 6-109.4	Exterior			all yard area	
<b>Violation:</b>	Disposal of rubbish, garbage and waste.				
<b>Notes:</b>	filled trash bags				
3) 6-109.4	Exterior			all yard area	
<b>Violation:</b>	Disposal of rubbish, garbage and waste.				
<b>Notes:</b>	stacks of old newspapers				
4) 6-109.4	Exterior			all yard area	
<b>Violation:</b>	Disposal of rubbish, garbage and waste.				
<b>Notes:</b>	broken wooden crates				
5) 6-109.4	Exterior			all yard area	
<b>Violation:</b>	Disposal of rubbish, garbage and waste.				
<b>Notes:</b>	old plastic crates/boxes				
6) 6-109.4	Exterior			all yard area	
<b>Violation:</b>	Disposal of rubbish, garbage and waste.				
<b>Notes:</b>	old tires				
7) 6-109.4	Exterior			all yard area	
<b>Violation:</b>	Disposal of rubbish, garbage and waste.				
<b>Notes:</b>	broken trash receptacles				
8) 6-109.4	Exterior			all yard area	
<b>Violation:</b>	Disposal of rubbish, garbage and waste.				
<b>Notes:</b>	glass bottles				
9) 6-109.4	Exterior			all yard area	
<b>Violation:</b>	Disposal of rubbish, garbage and waste.				
<b>Notes:</b>	cement cinderblocks				
10) 6-109.4	Exterior			right yard	
<b>Violation:</b>	Disposal of rubbish, garbage and waste.				
<b>Notes:</b>	broken childrens playground equipment				

---

---

**CITY OF PORTLAND**  
**DEPARTMENT OF PLANNING & URBAN DEVELOPMENT**

389 Congress Street  
Portland, Maine 04101

---

**Inspection Violations**

<b>Owner/Manager</b> LUCARIELLO VINCENT E JR		<b>Inspector</b> Tom Markley	<b>Inspection Date</b> 12/8/2005
<b>Location</b> 74 ILLSLEY ST	<b>CBL</b> 167 E014001	<b>Status</b> Re-Inspect 30 Days	<b>Inspection Type</b> Building Permit-Housing Inspectio

11) 6-109.4 Exterior all yard area  
**Violation:** Disposal of rubbish, garbage and waste.  
**Notes:** miscellaneous trash/rubbish/debris

12) 6-109.5 Exterior all yard area  
**Violation:** Rodent and vermin control.  
**Notes:** piles of raked leaves and grass/ rodent harborage

13) 6-108.1 Exterior all house  
**Violation:** Foundations cellars, exterior walls, roofs  
**Notes:** paint peeling from trim and fascia board

14) 6-113.3 Exterior front porch  
**Violation:** Passageways and common stairway.  
**Notes:** electrical wiring hanging loose

15) 6-108.3 Exterior left rear  
**Violation:** Exterior windows, doors and skylights  
**Notes:** broken window

**Comments:**