Director of Planning and Urban Developmen Penny St. Louis Littel

> Inspection Services, Directo Tammy M. Munso

January 25, 2010

JONES PAUL C & 24 SHELBY LN SOUTH PORTLAND, ME 04106

CBL: 170 D001001 Located at 39 BYFIELD RD Certified Mail 7009 0820 0001 4187 9189

Dear JONES PAUL C &,

## STOP WORK ORDER

An evaluation of the above-referenced property on 01/26/2010 revealed that building construction was being conducted without benefit of a valid building permit as required by Section 105.1 of the 2003 International Building Code and the 2003 International Residential Code of the City of Portland.

Appropriate permitting has not been issued for the property listed above, therefore all construction activity at that property must STOP immediately. This is a STOP WORK ORDER pursuant to Section 114. of 2003 International Building Code and the 2003 International Residential Code of the City of Portland.

You may resume construction activity only after issuance of the appropriate building permit and the subsequent lifting of this order. Building Permit Applications are available in this office, Room 315 at Portland City Hall, from 8:00 a.m. to 4:00 p.m. weekdays except holidays.

Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code and in Title 30-A of M.R.S.A. Section 4452. This constitutes an appealable decision pursuant to Section112 of the City of Portland Building Code.

If you wish to discuss this matter, or you have any questions, please feel free to contact me.

Sincerely,

Suzanne Hunt @ (207) 874-8707 Building Inspector