



Reviewed for Code Compliance
Inspection Division
Approved with Conditions
Date: 09/10/15

Date:

30

30

30

30

30

30

1

24

1

1

1


19' 9"

1' 24" Pillar

Unobstructed For Heat Pipes

94"

Refrigerator



1/8" scale

Front views
of Back wall

Saint Rose's Rehab