

LeClair's Plumbing & Heating
221 Milt Brown Road
Standish, ME 04084
207-892-4747 office
207-318-1978 cell

10/25/16 Called to 27 Hillis Street, Portland, ME, to inspect plumbing for code requirement. Found bathroom sink to have no vent as required by code. Round 2" vent had been installed within distance of toilet and shower to meet code requirements

11/3/16 Cut out and installed all new plumbing PVC under lavatory sink with anti-siphon traps as required by code. Tested toilet/shower/and lavatory upon completion and all are working fine.

A handwritten signature in blue ink, appearing to read "J. LeClair", is centered on the page.

Don McClair, McClair Plumbing & Heating 11/3/16

- Called to 27 Hillis St
Portland Maine to inspect
Plumbing for code Required
Venting.
- Found Bathroom sink to have
no vent as Required by code
- Found 2" vent had been
Installed with a Distance
of toilet and shower to
meet code Requirements.
- Cut out and installed all New
Plumbing PVC under lavatory
sink with Anti siphon traps
as Requested by code
- Tested Toilet/Shower/and
lavatory upon completion. ~~and~~
~~Everything seems to work as~~
and is working Fine