

COMMENTS

1/10/01 Spoke to owner (no # for contractor) and explained that the plot plan was not correct (off by 23') - Owner will measure himself & call back - S

2/8/01 Measured setbacks with property owner 16' on side 38' on rear OK to pour measured sona tube depth OK mounting

3/2/03- Jun room completed & appears to be in compliance with conditions of permit

Closed

CBL # 176 - B - 8

permit # 010038

Inspection Record

Type	Date
Foundation: _____	_____
Framing: _____	_____
Plumbing: _____	_____
Final: _____	_____
Other: _____	_____