

## UPDATED INFO

① Front porch has no connectivity to the apartment, the apartment is only accessible from the side entry door, which is an existing 3'x4' porch with existing railing & security light (Motion sensor). The front porch only services the main house.

② The shared door/entry from the main house to the Apartment was closed up with 3/4" plywood and the cavity was filled with Roxul Comfortbatt (4") fireproof insulation.

③ Sec 1: Walls & Ceilings are drywall. There is no shared wall to the Main house.

Sec 2: Exterior walls are & ceiling are drywall (Existing), shared wall to the main house is plaster/lathe + OSB which was skim coated over... probably for the installation of kitchen cabinetry. It was all existing.

Sec 3: Ceiling is plaster & lathe that was covered with 12" x 12" tile. Exterior wall & Interior Shared wall (with the main house) are plaster & lathe and filled w/ densepack cellulose (for insulation on the exterior wall & soundproofing on the interior/shared wall).

④ There are no longer any interconnections of the 2 units.

