

8125103 Setbacks OK. Sono tubes 48" +. OK to PROCEED.

No one at home - Left Green tag OK

2/23/04 - work has been completed +
appears to meet the conditions of The permit
700A

Close and

Permit # 03-0996

CBL # 176-H-12