

COMMENTS

9/18/00 - Stop work order put on because no setback or footing/foundation inspection performed. I not called by contractor/owner

9/19/00 - Setback inspection performed - OK - 42 FT in rear - 32 ft in side - 38 FT in front - all string out by contractor - Foundation looks good but no footing inspection performed. Did not check for drainage / insulation ect ect. Tom M

12/12/00 Final inspection. All complete according to plans. Close permit JRL

Inspection Record		Date
Type		
Foundation:	_____	_____
Framing:	_____	_____
Plumbing:	_____	_____
Final:	_____	_____
Other:	_____	_____