



Replacing window and door on back of condo: Window being replaced with #2 on window & door schedule. Door being replaced is below window in the picture above, obscured by vegetation. A partial picture of the door is also below... Door is a French door and is being replaced with item #1 on the window and door schedule.

3 Windows on the front of the condo are being replaced...top window is being replaced with #3 on the window & door schedule and the two bottom windows are being replaced with #4 on the window & door schedule.

