

411210 - surveyor found pins on front - contractor shortned dicle
up with Amendment - sensor tubes 48" - setback on side
9'. OK go

Close out - see original permit
for notes.

CBL # 184-B-17

permit # 03-1094