## Portland, Maine



# Yes. Life's good here.

Danielle P. West-Chuhta Corporation Counsel

Michael I. Goldman Associate Counsel Anne M. Torregrossa Associate Counsel Victoria E. Morales Associate Counsel

December 2, 2016

#### NOTICE OF INTENT TO PROSECUTE

To Whom it May Concern,

Please see the attached Notice of Violation and Order to Correct from the City of Portland Fire Prevention Bureau. The Fire Prevention Bureau has referred this matter to me for prosecution in the event that you do not complete and return the required plan of action by the date contained in the Notice of Violation. Your failure to comply will result in the issuance of a summons for you to appear in court, and the imposition of civil penalties in the minimum amount of \$100 per violation per day.

Please contact the Fire Prevention Bureau at (207)874-8400 to resolve these outstanding violations. I look forward to your anticipated cooperation and appreciate your efforts to help keep the citizens of Portland safe.

Sincerely,

Anne M. Torregrossa

**Associate Corporation Counsel** 

hme Tonequoso

City of Portland

### CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

#### NOTICE OF VIOLATION AND ORDER TO CORRECT

December 2, 2016

Responsible Party 1: Lohmeyer Randa 107 CRESTVIEW DR PORTLAND, ME 04103 Responsible Party 2: Estate of RANDALL STEARNS 102 Woodfield Rd PORTLAND, ME 04102

Location	CBL	<b>Inspection Date</b>
486 WOODFORD ST	184 D019001	11/18/2016
Inspector	Inspection Type	Status
John Brennan	FP Routine Inspection	Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must complete the proposed date of completion column by proposing a reasonable timeframe to remedy each violation. This form must be received by the Fire Prevention Bureau no later than 12/30/2016. The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

YOUR FAILURE TO SUBMIT A PLAN OF ACTION BY THE DATE PROVIDED, OR TO CORRECT ANY VIOLATION WITHIN THE APPLICABLE TIME FRAME, MAY RESULT IN LEGAL ACTION AGAINST YOU, THE IMPOSITION OF CIVIL PENALTIES, AND THE PURSUIT OF OTHER LEGAL REMEDIES.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation.	//
All apartment doors must be labeled with the correct apartment number.  NFPA 101- 31.3.1.1.1 VERTICAL OPENINGS NOT FIRE RATED; Vertical openings shall be enclosed or protected in accordance with Section 8.6.  Attic hatch above the second floor landing in the front stairwell is not fire rated and found not to be in place to cover attic opening.	//
<b>NFPA 101- 7.5.1.1 EXIT OBSTRUCTED</b> ; Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4. There is storage in the front stairwell on the second floor landing as well as the rear exterior fire escape.	IMMEDIATELY remove all obstructions from the exits. Your signature below indicates that all obstructions have been removed and will not be replaced.
NFPA 101- 7.2.1.5.2 ILLEGAL LOCKS ON EXIT DOOR; Locks, if provided, shall not require the use of a key, a tool, or special knowledge or effort for operation from the egress side. The only entrance into the basement is an exterior door at the rear fire escape and that has a padlock on it. An occupant could unknowingly be locked in the basement from the outside.	IMMEDIATELY remove or disable all illegal locks on exit doors. Your signature below indicates that the illegal locks have been removed or disabled and will not be replaced.

Violation		<b>Proposed Date</b>
		of Completion
	COMBUSTIBLE LIQUIDS STORAGE EXCEED pecial occupancy limits for flammable and combustible the basement.	IMMEDIATELY remove all excess flammable/combustible material from the interior of the structure. Your signature below indicates that all excess material has been removed, will not be replaced, and will be properly disposed of or stored elsewhere.
equipment, including busbars, wiring terr damaged or contaminated by foreign ma corrosive residues. There shall be no day or mechanical strength of the equipment deteriorated by corrosion, chemical react Exposed wires found on top of the water	D WIRING CONNECTIONS; Internal parts of electrical minals, insulators, and other surfaces, shall not be terials such as paint, plaster, cleaners, abrasives, or maged parts that may adversely affect safe operation such as parts that are broken; bent; cut; or tion, or overheating.  heater. There are wires that do not terminate in an sement. The outlet closest to the basement sink is not	//
for missing box covers.	er to NFPA 70, National Electrical Code, on standards ng box covers near the storage area as well as in front	//
VIOLATOR CERTIFICATION		1
I agree to remedy the violations listed understand that I must contact the Fire entirely within the Bureau's discretion I further understand that it is my resp	within the timeframes provided. If I require addite Prevention Bureau prior to the deadline to requent to grant or deny.  onsibility to schedule a reinspection of my proper ure to schedule a reinspection shall be deemed an	est an extension, which is
1 0	t, I understand that I am liable for penalties pursua and 10-25, and 30-A M.R.S. § 4452 and may be	•
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		

Fire Prevention Bureau

Date