Reference for Building Cross Section

Inspections Division
Date: 01/17/14

No stairwells will be affected by this renovation. No load bearing walls will be removed or tampered with. Building has a center beam in basement which carries a full length wall (runs front to back of each unit) in each apartment unit.