CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date	
DENSMORE JOEL Y		Tom Markley	6/30/2005	
Locatation	CBL	Status	Inspection Type	
18 MASSACHUSETTS AV	186 D026001	Re-Inspect 30 Days	Complaint-Inspection	

	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date	
1)	6-109.4	Exterior	1		Porch		
	Violation:	Disposal of rubbish, garbage and waste.					
	Notes:	Rubbish - Garbage - extremely nasty on porch					
2)	6-109.5	Exterior	1		Porch		
	Violation:	Rodent and vermin control.					
	Notes:	es: Front Porch squirrels, rodents have food source on porch - squirrels all over porch					
3)	6-109.2	6-109.2 Exterior 1		Various locations			
	Violation:	Maintenance of shared areas.					
	Notes:	Side yard 2 unregisterd vehicles in yard (1) gray van & (1) Gray oldsmobile					
4)	6-108.4	Exterior			Porch		
	Violation:	Stairways, stairwells, stairs, porches.					
	Notes:	rotting trim on porch					
5)	6-108.4	Exterior			Porch		
	Violation:	tion: Stairways, stairwells, stairs, porches.					
	Notes:	broken handrail on porch					
6)	6-109.4	Exterior			Various locat	ions	
Violation: Disposal of rubbish, garbage and waste.							
	Notes:	Roof missing shingles					
	Commenter						

Comments: