CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager Joseph P. Guidi Locatation CBL				Inspector Chris Hanson Status		Inspection Date 11/6/2006 Inspection Type									
								20	0 MASSACH	USETTS A	186A F018001	Re-Inspect 10 Day	S	Building Permit-Close-in/Elec./Pl	
									Code	Int/Ext		Floor	Unit No.	Area	Compliance Date
1)	105.1 Violation:	Interior Building w/o	Permit	3	4	Deck	11/08/2006								
	Notes:	added 4th unit on 3rd floor no egress no smokes													
2)	6-111.1	Interior		3	4	Bathroom									
	Violation:	Plumbing sta	andards/Basic facilit	ies.											
	Notes:	Venting in bathroom not vented to exterior of bldg.													
3)	6-116.6	Interior		1		Basement	Basement								
	Violation:	Asbestos													
	Notes:														
4)	6-71	Interior				Various locations									
	Violation:	Enforcement for defective installa		ations											
	Notes:														

Plumbing done w/out permit Permit is pending 3rd floor added unit 1 means of eggress no smokes elect outlets directly above elect. Heat self closing hinges needed on fire rated door