

**CITY OF PORTLAND**  
**DEPARTMENT OF PLANNING & URBAN DEVELOPMENT**

389 Congress Street  
 Portland, Maine 04101

**Inspection Violations**

<b>Owner/Manager</b> Joseph P. Guidi		<b>Inspector</b> Chris Hanson	<b>Inspection Date</b> 11/6/2006
<b>Location</b> 200 MASSACHUSETTS A	<b>CBL</b> 186A F018001	<b>Status</b> Re-Inspect 10 Days	<b>Inspection Type</b> Building Permit-Close-in/Elec./PI

	<b>Code</b>	<b>Int/Ext</b>	<b>Floor</b>	<b>Unit No.</b>	<b>Area</b>	<b>Compliance Date</b>
1)	105.1	Interior	3	4	Deck	11/08/2006
	<b>Violation:</b> Building w/o Permit					
	<b>Notes:</b>					
2)	105.1	Interior	3	4	Deck	
	<b>Violation:</b> Building w/o Permit					
	<b>Notes:</b>					
3)	6-108.4	Interior	3	4	Deck	
	<b>Violation:</b> Stairways, stairwells, stairs, porches.					
	<b>Notes:</b>					
4)	6-110.2	Interior	3	4	Various locations	
	<b>Violation:</b> Efficiency apartments.					
	<b>Notes:</b>					
5)	6-110.5	Interior	3	4	Attic	
	<b>Violation:</b> Computation of floor area.					
	<b>Notes:</b>					
6)	6-111.1	Interior	3	4	Bathroom	
	<b>Violation:</b> Plumbing standards/Basic facilities.					
	<b>Notes:</b>					
7)	6-116.2	Interior	3	4	Various locations	
	<b>Violation:</b> Egress					
	<b>Notes:</b>					
8)	6-116.6	Interior	1		Basement	
	<b>Violation:</b> Asbestos					
	<b>Notes:</b>					
9)	6-71	Interior			Various locations	
	<b>Violation:</b> Enforcement for defective installations					
	<b>Notes:</b>					

**Comments:** Furnace not vented in basement needs to be disconnected Needs permits to remove asbestos  
 Plumbing done w/out permit Permit is pending 3rd floor added unit 1 means of egress no smokes  
 elect outlets directly above elect. Heat self closing hinges needed on fire rated door