## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

July 24, 2017



Location	CBL	Inspection Date
232 BRIGHTON AVE	186A F019001	10/19/2016
Inspector	Inspection Type	Status
Christopher Goodall	FP Routine Inspection	Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 8/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion	
NFPA 10- 7.2.4.4 FIRE EXTINGUISHER INSPECTION TAG; Where manual inspections are conducted, records for manual inspections shall be kept on a tag or label attached to the fire extinguisher, on an inspection checklist maintained on file, or by an electronic method. Extinguisher in front hall stariwell second floor landing needs tag	//	Completel
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.  1. Smoke detector 2nd floor landing rear needs replacement. 2. Smoke detector thrid floor landing front needs replacement. 3. Loose smoke detector sitting on front porch railing. 4. Smoke detector in rear stairwell needs new battery.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.	complete 1
NFPA 1 EXCESSIVE/DISORDERLY STORAGE; Reference NFPA 1 for excessive fuel-load.  Second floor landing front stairwell	_/_/_	Complete &
NFPA 70- ARTICLE 110 B CERTIFY ELECTRICAL SYSTEM; Listed or labeled equipment shall be installed and used in accordance with any instructions included in the listing or labeling. Entire electrical system needs to be looked at.  Washing machine located in front of electrical panel	//	completel
NFPA 70 MISSING BREAKER IN PANEL; Refer to NFPA 70, National Electrical Code, for information on missing breakers in an electrical panel.  3rd floor panel has missing breaker	//	completed

Violation	Proposed Date of Completion	
NFPA 101- 8.3.4.2 60 MINUTE FIRE DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 that states fire door assemblies for vertical shafts (including stairways, exits, and refuse chutes) are rated and required for 1 hour.  Rear stairwell to basement	11/1/17	- (lease
FINAL DATE OF COMPLETED VIOLATION(S)	//	This ca
FIRE PREVENTION BUREAU RE-INSPECTION OF COMPLETED VIOLATION(S)	//	15378
The Bureau reserves the right to reject or modify any proposed plan of action, and may sufficient financial and technical capacity to complete the proposed plan. Please contact questions.  VIOLATOR CERTIFICATION		. • • •
I agree to remedy the violations listed within the timeframes provided. If I require addi understand that I must contact the Fire Prevention Bureau <u>prior to the deadline</u> to requ is entirely within the Bureau's discretion to grant or deny.	itional time to comply, I test an extension, which	
I further understand that it is my responsibility to schedule a reinspection of my proper	rty once the violations	

have been remedied to do so. My failure to schedule a reinspection shall be deemed an admission that the

action.	and 10-25, and 30-A M.R.S. § 4452 and may be subjection
Date /	Responsible Party
Date	Responsible Party
SEEN AND AGREED  Sibility Date	CAPT B 5# 17 Fire Prevention Bureau

violations have not been remedied.