



Photo 1. Deck, steps to deck, and door to house, all to be removed. 11 Stevens Avenue, Portland, ME. Photo taken April 30, 2016.



Photo 2. Closer view of collapsed area at center of deck. The door will be removed, the opening filled in (framed, sheathed) and finished with wood shingles matching the existing. 11 Stevens Avenue, Portland, ME. Photo taken April 30, 2016.