

COMMENTS

01/16/04 - work has been completed & appears to meet the requirements of the permit. J.M.

CBL# 190-D-1  
Permit # 05 1140

John - out

Inspection Record

Type

Date

Foundation:

Framing:

Plumbing:

Final:

Other: