

5-7 Davis Street

190-G-1



SHAW-WALKER

8503-3R

September 24, 1979 X

Joseph J. & Yvette J. Doyle, Jts.
5-7 Davis Street
Portland, Maine 04102

Dear Mr. & Mrs. Doyle:

Re: 5-7 Davis Street - 190-G-1
NCP-Libbytown

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,
Joseph E. Gray, Jr., Director
Neighborhood Conservation

By Lyle A. Noyes
Lyle A. Noyes,
Chief of Housing Inspections

Inspector M. Leary

/88

City of Portland

NEIGHBORHOOD CONSERVATION
Check Off Sheet
STRUCTURE INSPECTION SCHEDULE

Housing Inspection Division

2) Insp. Name M. Lezina

1) Insp. Date 9-13-77 3) Insp. Type Libb House 4) Proj. Code Libb House 5) Assr's Chart 190 6) Bl. 2 7) Lot 1 8) Census Tract 1 9) Blk. 1 10) Insp. 1 11) Form No. 1

12) Hous. No. 5-11 13) Sec. H. No. 1 14) Suff. 1 15) Direct 1 16) Street Name Davis 17) St. Design. 1

18) Owner or Agent: Mrs. Mrs. Joseph J. & Yvette J. Doyle Jr. 19) Status 00 20) Bldg's Rat. 1

21) Address: 7 Davis Street

22) City and State: Portland, Maine Zip Code 04102

23) D. Units 2 24) Occ. D. U's 2 25) Rm Units 2 26) Occ. R. U.s 2 27) No. Occupants 2 28) Con'l L. 1 29) Bldg. Type 1 30) Stories 2 31) Const. Mat. 1 32) O. B's 1

33) C. H. 1 34) Plo. 1 35) Zoned For 1 36) Actual Land Use 1 37) D. D. 1 38) Lks. Ad. Bth. Fac. 1 39) Disp. 1 40) Closing Date 1

EXTERIOR - Structure			INTERIOR - Structure		
		Cd. Viol.			Cd. Viol.
Foundation	EX/FO	3a	Light	LI	8
Wall	EX/WA	3a	Elec. Wiring	EW	8e
Roof	RO	3a	Floors	FL	3b
Porch	PO	3d	Walls	IN/WA	3b
Stairs	EX/SR	3d	Ceilings	CE	3b
Steps	SP	3d	Windows	IN/WI	3c
Doors	DO	3c	Airshafts	AS	3c
Windows	EX/WI	3c	Roof Rafters	ROR	3a
Eaves	EA	3a	Sanitation	SAN	4e
Trim	TR	3a	Stairways	IN/SRW	3d
Chimney	EX/CH	3e	Stair Treads	SRT	3d
Gutters	GU	3a	Wastelines	WSL	6d
Roof Drains	RD	3a	Supply Lines	SUL	6c
Bulkhead	BU	3d	Stacks	ST	3e
Outbuildings	GR - SH	4e	Flues	FU	3e
Yard	YA		Vents	VE	3e
Garbage	GA	4d	Chimney	IN/Ch	3e
Rubbish	RU	4d	Heating Equip. Furnace - FU	Spaceheater - SPH	9c
Containers	CO	4d	Bsmt. Sanitation Litter - LI	Debris - DE	4b
Drainage	DR	3a	Dampness - DM		3a
Infestation	IN-CR-FL	4e	Lighting	BS/LI	8c
Rats	RA	4e	Elec. Panel	EL/PA	8e
Other		4e	Stairs	ES/SR	3d
Fire Escape	FE	10	Foundation	IN/FO	3a
Dual Egress	DE	10	Floor Joists	FL/JO	3a
Driveways	DW		Carrying Timbers	CA/TI	3a
Walks	WA		Sills	SI	3a
Landscaping	FN		Bsmt. D. U. Conforms BDU		5f

Remarks on reverse side

