DISPLAY THIS CARD ON PRINCIPAL FRONTAGE OF WORK



CITY OF PORTLAND BUILDING PERMIT



This is to certify that

BABKIRK DOUGLAS & BARBARA S BABKIRK JTS

55 REDLON PARK RD

PERMIT ID: 2017-01461

ISSUE DATE: 09/20/2017

CBL: 193 E032001

Located at

has permission to Install Mitsubishi mini split heat pump.

provided that the person or persons, firm or corporation accepting this permit shall comply with all of the provisions of the Statues of Maine and of the Ordinances of the City of Portland regulating the construction, maintenance and use of the buildings and structures, and of the application on file in the department.

Notification of inspection and written permission procured before this building or part thereof is lathed or otherwise closed-in. 48 hour notice is required.

A final inspection must be completed before this building or part thereof is occupied. If a certificate of occupancy is required, it must be procured prior to occupancy.

N/A /s/ Michael Russell, MS, Director

Fire Official Building Official

THIS CARD MUST BE POSTED ON THE STREET SIDE OF THE PROPERTY THERE IS A PENALTY FOR REMOVING THIS CARD

Approved Property Use - Zoning

Building Inspections

Fire Department

PERMIT ID: 2017-01461 **Located at:** 55 REDLON PARK RD **CBL:** 193 E032001

BUILDING PERMIT INSPECTION PROCEDURES Please call 874-8703

or email: buildinginspections@portlandmaine.gov

Check the Status of Permit or Schedule an Inspection at http://www.portlandmaine.gov/planning/permitstatus.asp

With the issuance of this permit, the owner, builder or their designee is required to provide adequate notice to the City of Portland Inspections Division for the inspections listed below. Appointments must be requested 48 to 72 hours in advance. The inspection date will need to be confirmed by this office.

- Please read the conditions of approval that are attached to this permit.
- Permits expire in 6 months if the project is not started or ceases for 6 months.
- If the inspection requirements below are not followed, then additional fees may be incurred due to the issuance of a "Stop Work Order" and subsequent release to continue.
- Per Section 107.3.1 of the Maine Uniform Building and Energy Code (MUBEC), one set of printed approved stamped construction documents will be kept at the site of work and open to inspection by building officials.

REQUIRED INSPECTIONS:

Electrical - Residential Close-in Plumbing/Framing Final Inspection

The project cannot move to the next phase prior to the required inspection and approval to continue.

If the permit requires a certificate of occupancy, it must be paid and issued to the owner or designee before the space may be occupied.

PERMIT ID: 2017-01461 **Located at:** 55 REDLON PARK RD **CBL:** 193 E032001

city of a ordinary frame. During of ego a crimit			1			
389 Congress Street, 04101 Tel: (207) 874-8703, Fax: (207) 874-8716			2017-01461	09/14/2017	193 E032001	
Proposed Use:		Proposed	Proposed Project Description:			
Same. Single Family.			Install Mitsubishi mini split heat pump.			
Dent: Fast Track	Status: Approved w/Conditions	Reviewer:	Keri Ouellette	Approval D	Date: 09/20/2017	

Permit No:

Date Applied For:

CBL:

Ok to Issue:

Conditions:

Note:

- 1) Carbon Monoxide Alarms: Where required in existing dwellings. Where work requiring a permit occurs in existing dwellings that have attached garages or in existing dwellings within which fuel-fired appliances exist, carbon monoxide alarms shall be provided in accordance with Section R315.1.
 - A separate permit is required for any electrical work.

City of Portland, Maine - Ruilding or Use Permit

- The installation must comply with the Manufacturers' Listing, and MUBEC (IRC, 2009).
- 2) The review of this permit did not include a review or confirmation of the zoning legal use. It is only approving the specific work described in the plans and forms submitted. The current use of the property may be found to be unlawful.
- 3) Separate permits are required for any electrical, plumbing, sprinkler, fire alarm, HVAC systems, heating appliances, including pellet/wood stoves, commercial hood exhaust systems, fire suppression and fuel tanks. Separate plans may need to be submitted for approval as a part of this process.
- 4) This is being issued with the understanding that as a fast track, the owner is responsible for scheduling inspections for the work being done and the inspector may require modifications to the work that has been completed if it does not meet code.
- 5) This permit is being approved on the basis of plans submitted. Any deviations shall require a separate approval before starting that work.

PERMIT ID: 2017-01461 **Located at:** 55 REDLON PARK RD **CBL:** 193 E032001