



*Why wait? Call Pine State!*

- ✓ PLUMBING ✓ HEATING
- ✓ COOLING ✓ SEWER & DRAIN

Suzanne Russo  
50 Eastfield Road  
Portland, ME 04102

7/9/2014

Dear Suzanne,

Please find this letter as evidence of a plumbing inspection of your pool house located at 50 Eastfield Road in Portland Maine. On 7/8/2014, Pine State Services was hired to give our professional opinion and perform a plumbing inspection of the previous work done by another company.

Our technician inspected the ½ bathroom lavatory sink and toilet. The Saniflo pump system 1" discharge tying into 3" branch drain is separately vented at pool house 1.5" vent. **System is up to code.**

Please let our office know if you are have any other questions.

Thank you!

A handwritten signature in black ink, appearing to read "S. Marosso", is written over the "Thank you!" text.

Samuel Marosso  
Master Plumber Lic. # MS2501  
Pine State Services  
184 Main Street  
South Portland, ME 04106