-Page 1

5 Richardson Lane, Stoneham, MA 02180 781-438-7755 (Voice) 781-438-6216 (Fax)

Ultrasonic Inspection Report

Matt Grady

R. W. Gillespie & Assoc. Inc.

86 Industrial Park Road

Suite 4

Saco, ME 04072

Report Date 10/29/2010

Report No. 1

Job Number 13905

Portland, ME

Contractor Turner Construction

Test Method Standard: AWS-D1.1-10 Acceptance Standard: AWS-D1.1-10							UT Unit Serial No.: USN-50 600160									
							Thickness: Varies									
								Decibels			Discontinuity					
Weld				Indication Number	Transducer Angle (Degrees)	From Face								Depth From "A" Surface	Distance	
	Meets Code	Fails Code	Procedure Legend					Indication Level	Reference Load	Attenuation Factor	Indication Rating	Length	Angular Distance		From	From
ID/Location		_					Leg	а	b	С	d	۳	Ā	Ď	Х	Y
Elevation: (S02.0		(L		5,	zone			s only								1
XC/Z5 east	Х		1		70	Α	1		65							
XC/Z4 east	Х		1		70	A	1		65							
XC/Z4 west	Х		1		70	A	1		65							
XC/Z3 west	Х		1		70	Α	1		65							
XD/Z5 east	X	-	1		70	A	1		65							
XD/Z4 east	X	-	1	-	70	A	1		65							
XD/Z4 west	X	-	1	-	70	A	1		65							
XD/Z3 west	Х	<u> </u>	1	<u> </u>	70	Α	1		65	<u> </u>						1
Couplant: Exosen								Frequency 2.25 MHz								
Calibration Technic	ian: F	. J	ones							Surface	Condit	ions: A	s Wel	ded		
Technician: F. Jones Level: II								Interpreter: F. Jones Leve					_evel: II			

GENERAL REMARKS:

Inspector	Premium	Hours	Travel
Name	Time		Time
F. Jones	No	Max Day	

REVIEWED BY: William P. Crabtree

UNC

Our reports are available in PDF form via email. Please email us at reports@utsofmass.com for more information.

cc: